

FAAC-INFO

TECHNICAL SERVICES DEPT.

Date: November 2, 2005	Vol. # 011
Subject: 400/422 Swing Gate Operators	Reason For Info: Modifications

Description:

FAAC is proud to introduce some modifications to our model 400 Swing gate operators.

These modifications are as follows:

- 1) * The locking cap has been changed to prevent the home owners from being able to turn the key too far counterclockwise compromising the key cylinder. This modification also improves sealing of the operator. I have attached a picture to show the new style manual release system.
- 2) The valve body has had a pressure relief spring added to it in the event a customer uses the wrong oil and causes a lock up situation. This relief spring also makes it so that during installation, the installer does not have to set the pressures different from one another.
- 3) The valve body has also been modified to incorporate a new inlet valve. This inlet valve allows a more even flow of oil in the hydraulic system. This will result in identical opening and closing speeds.

The start of production with these modifications is January 2006.

***Please visit our web site at faacusa.com for further details on this modification.**

